

GE Monogram

General Electric Company Appliance Park, Louisville, KY 40225

Service Bulletin


REF 02-01 REFRIGERATORS ZISW36DC ZISW42DC ZISW48DC ZISB36DC ZISB42DC ZISB48DC ZISS36DC ZISS42DC ZISS48DC ZIS36NC **ZIS48NC** ZIS42NC ZISS36NC ZISS42NC ZISS48NC **WATER SYSTEM DIAGRAM**

FEBRUARY 2001

Fill Tube Freezing Up

In February of 2000, a water filter was added to our Monogram side-by-side models. The following diagram will help to better identify leak locations.

- 1. Brass coupling
- 2. Copper extension
- 3. Elbow connector at water valve (orange)
 - a) leaking at valve
 - b) leaking at tubing
- 4. Water filter
- 5. Elbow connector at water valve (brown)
 - a) leaking at valve
 - b) leaking at tubing
- 6. Elbow connector at water valve (1/4")
 - a) leaking at valve
 - b) leaking at tubing
- 7. Plastic tube at fill grommet
- 8. Fill cup, fill tube
- 9. Icemaker
- Elbow connector at water valve (5/16")
 - a) leaking at valve
 - b) leaking at tubing
- 11. Water tank
- 12. 5/16" to 1/4" connector tank to door
- 13. Tube @ dispenser



Please message one of the following Product Quality Engineers with leak locations after repairs have been completed.

L010215 or mike.hamilton@appl.ge.com L097360 or jim.rockwell@appl.ge.com