

Service Bulletin

MARCH 2007

REFRIGERATORS
SIDE-BY-SIDE PLASTIC LINER MODELS
(MODELS LISTED BELOW)

REF 05-07

REFRIGERATOR WILL NOT CARRY THE HARNESS DC CAPACITORS (WR23X10494 AND WR23X10495)



Models Affected:

The following Side-by-Side Plastic Liner Models will not carry the Harness DC Capacitors **WR23X10494** and **WR23X10495**.

GCE21IE	GCU23MI	PIE25NG
GCE21LG	GIE21IE	PJE25MG
GCE21MG	GIE21LG	PJE25PG
GCE21SI	GIE21MG	PSE25NG
GCE21YE	GIE21YE	PSE25SG
GCE21ZE	GTE22FB	PSE27MG
GCE21ZG	GTE22IB	PSE27NG
GCE23LB	GTE22JB	PSE27NH
GCE23LG	GTE25DB	PSE29NH
GCE23LH	GWE23LG	PTE22LB
GCE23YB	PCE23NG	PTE22SB
GCE23YE	PCE23NH	PTE25LB
GCE23YH	PCE23YE	PTE25SB
GCU21LG	PHE25MG	ZCE23SG
GCU21YE	PHE25PG	ZSE27SG

Currently there are Harness DC Capacitors (**WR23X10494** and **WR23X10495**) in the main board area on the International Side-by-Side Plastic Liner Models.

Improvements have been made in the main board and it has been determined that the EMI Noise Filters (Capacitors) will not need to be used on the units. See illustrations below:



GE Appliances
General Electric Company
Louisville, Kentucky 40225

GE CONFIDENTIAL AND PROPRIETARY INFORMATION—NOT FOR PUBLIC DISCLOSURE