

SERVICE BULLETIN

Dryer

Dryer

LG Electronics Inc.

Date of issue: 18. May. 2004.

Buyer Model : DLE5932W, DLE2532W, DLE0332W, DLE5932S, DLE3777W , DLE5977W

LGE Model : TD-V10030E, TD-V10031E, TD-V10032E, TD-V10035E, TD-V10051E ,TD-V10050E


Buyer Name : LGEUS, LGECI, LGEMS, LGEPS

Effective Date : 18. MAY. 2004.

Applicable Serial No. : From Dec. 2002 To APR. 2004 production Lot.

Subject : When you service thermostat, change the heater connector.

Phenomenon



Heater

* Interchangeability Code	Alphabetic Code	Numeral Code
A	Interchangeable: Old and new parts can be used in products as the bulletin regardless of manufacturing date.	1 To improve performance
B	Old parts can be substituted for new :Old parts can be used in products regardless of manufacture date. New parts can be used in new products only.	2 To improve productivity
C	New parts can be substituted for old parts : Only new parts can be used in products regardless of manufacture date.	3 To improve reliability
D	Not interchangeable : New parts can be used in new products only.	4 Change of material or dimension
		5 Addition
		6 Deletion
		7 Correction