

Service Bulletin



No: 2002-25

Date: 07/18/02

Complaint: Refrigerator and freezer lights overheat causing light shield and control panel to warp.

Models affected: ****362/482 Bottom Mount and Side-by-Side refrigerator/freezers
 ****363/483 Bottom Mount and Side-by-Side refrigerator/freezers (products manufactured before 05/09/02. Light Thermal Kit installed in products manufactured on/after 05/09/02)

Correction: Install Light Thermal Kit (#G5098071) as shown in illustrations below:

Kit consists of:

QTY	PART NUMBER	DESCRIPTION
2	PE970353	Thermal Protector
2	M0102804	Bracket (Clip)
2	M0230028	Screw
1	G4098431	Jumper Wire
1	F90158	Installation Instructions

Installation Steps:

1. Remove the light shield to expose the wiring to the light socket and light switch.
2. Drill a mounting hole for the Bracket (clip) as shown in ①
3. Install Thermal Protector using the Bracket (clip) and Screw provided.
4. Connect the Thermal Protector between the light socket and the light switch as shown below. ②

